

COST OF REPAIRS

A modern PEUGEOT is extremely complex, made up of many sophisticated moving parts. Which means that should your vehicle suffer a mechanical or electrical failure, the cost of repairs can be an unwelcome expense.

The examples below are taken from a sample of PEUGEOT repairs from 2017*, and reflect the average repair bills from various dealers throughout the country.

YOU COULD AVOID COSTS LIKE THESE WITH A PEUGEOT EXTENDED WARRANTY.

£670	Alternator
£99	Ignition Coil
£1015	Turbo Charger
£577	Starter Motor
£1219	Cylinder Head Gasket



PICKING UP THE BILL IF YOUR CAR FAILS ITS NEXT MOT

MOT Test Insurance

If your vehicle fails to pass its next MOT test due to failure of any part listed on a VT30* (MOT Test Failure Form), PEUGEOT MOT Test Insurance will pay up to £750 (including VAT) to cover the cost of repair of the following items:

Lighting Equipment

Lamps, reflectors, indicators and bulbs are covered for failure due to: Breakage, discoloration, misalignment, water ingress and corrosion.

Steering and Suspension

Manual and power steering units, suspension drags links, track rods/ends, transmission shafts, shock absorbers, road springs, wishbones, swivel joints, mountings, sub-frames and wheel bearings are covered for failure due to: Wear, seizure, leakage and insecurity.

Fuel System

Fuel injection system, fuel ECU and fuel pipes are covered for failure to meet MOT exhaust gas emission standards (actual tuning and adjustments or any damage caused by contaminated fuel are not covered under this section). Fuel leaks are not covered.

Braking System

Brake master cylinder, wheel cylinders, calipers, discs, drums, load compensator, ABS modulator/sensors/computers and brake pipe, hoses, cables are covered for failure due to wear, leakage, seizure, splits/cracks, corrosion and adjustment.

Seat Belts

Mountings, belts, retractors and buckles are covered for failure due to: wear, non-function and insecurity.

Vehicle Structure

Vehicle structure is covered for corrosion. Failure due to accident damage is specifically excluded.

General

Windscreen wipers, windscreen wiper motor, washer motors and horn.

- In Northern Ireland your authorised PEUGEOT repairer will carry out a pre-test MOT inspection, and will submit your vehicle for the MOT test on your behalf.
- Only one MOT Test Insurance claim is permissible during each 12 month warranty period.
- The MOT Test Insurance Policy does not cover accidental or malicious damage, neglect or normal in-service wear and tear.



PEUGEOT Extended Warranty Administration
Jubilee House
5 Mid Point Business Park
Thornbury
West Yorkshire
BD3 7AG
May 2018
Stock code: 9114
PB09270

EXPERTISE **BUILT IN**



EXPERTISE **BUILT IN**



PROTECTING YOUR VEHICLE

The older a vehicle becomes, the higher the risk of mechanical or electrical failure. Repairs can be costly and are generally unexpected.

You could avoid costs like these with a PEUGEOT Extended Warranty.



